

**EXHIBIT “B”**



REPAIR ORDER 7434-155812

RO DATE: 01/03/2012 VEHICLE:

491646

MILEAGE: 237679

PAGE 2 OF 3

JOB NO. 3	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE	CODE	PART/TIRE TAG NO.	PART DESCRIPTION	UNIT PRICE	QTY	TOTAL
COMPLAINT SCHEDULED PM		REBILL <input type="checkbox"/>	MODEL							
		RE/PM CODE 19 - T1	SERIAL NUMBER							
CAUSE DUE		PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS	ON ROAD HOURS						
		.70								
CORRECTION COMPLETE T1 PM - TRAILER		PARTS REBILL \$	LABOR REBILL \$	TECH(S) PATRICK						
NOTES PERFORM 27-POINT PREVENTIVE MAINTENANCE INSPECTION (INCLUDES, BRAKES, TIRES, ELECTRICAL SYSTEM, AXLES, ETC.); DOCUMENT ADDITIONAL REPAIRS NEEDED										
JOB NO. 4	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE						
COMPLAINT LIFTGATE INOP		REBILL <input type="checkbox"/>	MODEL							
		RE/PM CODE 55	SERIAL NUMBER							
CAUSE WIRING		PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS	ON ROAD HOURS						
		.30								
CORRECTION REPAIR LIFT GATE WIRING		PARTS REBILL \$	LABOR REBILL \$	TECH(S) PATRICK						
NOTES REPAIR LIFT GATE WIRING AS NEEDED; SECURE WIRING AND VERIFY PROPER OPERATION										
JOB NO. 5	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE						
COMPLAINT REPLACE BATTERIES		REBILL <input type="checkbox"/>	MODEL							
		RE/PM CODE 52	SERIAL NUMBER							
CAUSE FAILED LOAD TESTING		PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS	ON ROAD HOURS						
		1.10								
CORRECTION REPLACE BATTERY		PARTS REBILL \$	LABOR REBILL \$	TECH(S) PATRICK						
NOTES CHECK BATTERY; INSPECT AND CLEAN BATTERY CABLES; REMOVE AND REPLACE BATTERY; REASSEMBLE; CHECK CRANKING SYSTEM TO VERIFY PROPER OPERATION										



## REPAIR ORDER 7434-155812

RO DATE: 01/03/2012 VEHICLE:

491646

MILEAGE: 237679

PAGE 3 OF 3

JOB NO.	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE	CODE	PART/TIME TAG NO.	PART DESCRIPTION	UNIT PRICE	QTY	TOTAL
COMPLAINT	REEFER DOORS DON'T CLOSE	<input type="checkbox"/> REBILL <input type="checkbox"/>	MODEL							
		REP/PM CODE 82	SERIAL NUMBER							
CAUSE	LATCHES WORN OUT	PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS ON ROAD HOURS							
		.70								
CORRECTION	REPLACE DOOR LATCH	PARTS REBILL \$	LABOR REBILL \$	TECH(S) PATRICK						
NOTES REPLACE DOOR LATCH ON REFRIGERATION UNIT ENCLOSURE										
JOB NO.	7	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE					
COMPLAINT	ADJ BELTS	<input type="checkbox"/> REBILL <input type="checkbox"/>	MODEL							
		REP/PM CODE 82	SERIAL NUMBER							
CAUSE	LOOSE	PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS ON ROAD HOURS							
		.50								
CORRECTION	ADJUST BELTS ON REEFER UNIT	PARTS REBILL \$	LABOR REBILL \$	TECH(S) PATRICK						
NOTES ADJUST BELT TENSIONS ON REFRIGERATION UNIT TO PROPER SPEC AS NEEDED										
JOB NO.	GOAL	<input type="checkbox"/> WARRANTY	YEAR	MAKE						
COMPLAINT		<input type="checkbox"/> REBILL <input type="checkbox"/>	MODEL							
		REP/PM CODE	SERIAL NUMBER							
CAUSE		PARTS COST	PARTS RETAINED Y/N <input type="checkbox"/>							
		TECH HOURS	CUST SVC HOURS ON ROAD HOURS							
CORRECTION		PARTS REBILL \$	LABOR REBILL \$	TECH(S)						
NOTES										

[illegible]